

2008 Mazda RX 8 DTC: C1306

Steering Angle Sensor Calibration

DTC: C1306, Steering wheel angle sensor zero position not found

Commonly happens after battery dead or disconnected

1. Reconnect Battery
2. Turn ignition switch to ON, not run (don't start engine)
3. Turn steering wheel full right to stop
4. Turn steering wheel full left to stop
5. Return steering wheel to center
6. Erase any DTCs with a scanner
7. Start engine and verify repair